

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program April 5, 2011

Reviewed:

Mine Name: Lisbon Valley MinePermit Number: M/037/0088Operator Name: Lisbon Valley Mining Company LLCInspection Date: 03/29 & 3/30/2011Inspector(s): Tom MunsonTime: 7AMOther Participants: Lantz IndergardMine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds			
2. Public Safety (shafts, adits, trash, signs, highwalls)3. Protection of Drainages / Erosion Control		Н	H
4. Deleterious Material	H	H	H
5. Roads (maintenance, surfacing, dust control, safety)			
6. Reclamation		\boxtimes	
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8. Soils			
9. Revegetation			
10. Other			

Permit fee: Current Bond Renewal Date: Bond Amount: \$6,076,888

<u>Purpose of Inspection</u>: To perform a site inspection and work towards consolidation of an updated permit.

Weather: Sunny

Inspection Summary:

I meet with Lantz Indergard, mine manager, on the afternoon of the 29th and again in the morning of 30th to assist in bring the mine permit into a format acceptable to the operator and the Division. We performed field work looking at a drilling site within the GTO pit, the newly constructed sediment ditch at the base of waste dump C, and the site of non toxic material being removed from the upper benches of the Centennial Pit to construct the new haul road being built from the leach pad to the water tank.

I also reviewed an example permit format with Lantz that I had copied on a portable hard drive. We downloaded this example permit on his computer and reviewed its table of contents to help him understand the Division's needs. We also reviewed Paul Baker's example permit application explanation worksheet. Lantz said there appeared to be enough information to help him complete his new permit and he felt he didn't need much more explanation.

Regrading of Waste Dump C was taking place on the North end, second and third lift. I discussed how beneficial cross ripping would be instead of dozer tracking up and down the slope and how important the establishment of vegetation will be in determining future expansion on any



Inspection Date: 03/29/2011

Page 2 of 4 M/037/0088

dumps. We also drove to the bottom of the Sentinel West Pit and observed the pit pool. We discussed the benefits of having this pit filled in and recon toured to blend into waste dump C. We discussed that given there is plenty of non acid generating waste to back fill the pit with, water quality would not be a problem.

The following day we reviewed current amendments to the permit and their status both in regards to the Division's approvals and their approval with the BLM. We discussed future plans with expansion of Lisbon Valley both to the North and South and a future meeting with the BLM on April 13, 2011. Photos were taken to document site conditions.

Conclusions and Recommendations:

The purpose of this inspection was to further the process of obtaining a more up to date permit and consolidating past submittals and amendments.

Inspector's Signature


TM: eb

cc: rebecca_doolittle@blm.gov

O:\M037-SanJuan\M0370088-LisbonValley-Summo\inspections\insp-03292011A.doc

Inspection Date: 03/29/2011

Page 3 of 4 S/037/0088



Inspection Date: 03/29/2011

Page 4 of 4 S/037/0088

